

3261

T2S, R1W, U.S.M.

Section Corner:
Found 5/8" rebar in center of paved road.
Replaced 5/8" rebar with a 2.5", 2015
Aluminum cap (Stamped LS 8704293) on a
3/4" rebar flush with road surface. As
Reference Points to the Monument we set
2, 5/8" Rebar's with Blue Plastic Caps
Stamped (LS 8704293) which bear
N56°04'07"E 51.95' and S59°13'17"E
54.18' from the corner.

North 1/16 Corner:
Found no remaining evidence of Corner Monument nor its accessories. Used information from Survey Plat # 2518 to reposition 1/16 Corner. At the point for the 1/16 corner we set a 2.5", 2015 Aluminum cap (Stamped LS 8704293) on a 3/4" rebar protruding 0.3' above ground.

S19 | S20

Witness Corner:
Found no remaining evidence of Corner Monument nor its accessories. Used information from Survey Plat # 2518 to reposition 1/4 corner. Because of a ditch we were unable to monument the 1/4 corner. As shown here on we set a Witness Corner for the 1/4 corner. To monument the Witness Corner we set a 3", 2015 aluminum cap (Stamped LS 8704293) on a 3/4" rebar flush with ground. As Reference Points to the Witness Corner Monument we set 2, 5/8" Rebar's with Blue Plastic Caps Stamped (LS 8704293) which bear N89°25'42"E S2.92' and S20°33'22"E 60.84' from the Witness Corner.

Sec. 19

South 1/16 Corner:
Found and accepted 2.5"
Duchesne County Surveyor
Brass cap, flush with surface
of road.

Center South 1/16 Corner:
Found and accepted 1.5" Aluminum
cap (Stamped LS 148951) on 5/8"
rebar protruding 0.5' above ground.
North/South running fence line 1.0'
East of cap.

S89°54'25"W - 2630.11' (Tie-only)

1/16 Corner:
Found no remaining evidence
of corner monument nor its
accessories. Determined the
position of the corner to be at
proportionate distance.

16 Corner:
and accepted 2.5" Duchesne
Surveyor Aluminum cap protruding
ve ground, surrounded by a mound
s. 1.3' base, 0.4' high.

East 1/16 Corner: S30
Found and accepted 2.5" Duchesne
County Surveyor Aluminum cap
protruding 0.3' above ground, surrounded
by a mound of stones, 2.0' base, 0.6' high.

South 1/16 Corner: S19 + S20
Found no remaining evidence of Corner Monument nor its accessories. Used information from Survey Plat # 2518 to reposition 1/16 Corner. As a monument for the 1/16 corner we set a 2.5", 2015 Aluminum cap (Stamped LS 8704293) on a 3/4" rebar protruding 0.2' above ground.

West 1/16 Corner: S29
Found no remaining evidence of Corner Monument nor its accessories. Determined the point for the 1/16 corner to be in line with north running fence and midway between East West right-of-way fence lines. As a monument for the 1/16 corner we set a 2.5", 2015 aluminum cap (Stamped LS 8704293) on a 3/4" rebar protruding 0.5' above ground.

Center South 1/16 Corner:
Found and accepted Orange Plastic
Cap (Stamped LS 148951) on 5/8"
rebar protruding 0.6' above ground,
inline with North South running fence
and 0.4' south of East West running
fence

Southeast 1/16 Corner:
Found and accepted 5/8" rebar at a
3-way fence corner, fences running
South, East & West. Replaced 5/8" $\frac{1}{2}$
with a 2.5", 2015 Aluminum cap on
rebar protruding 0.4' above ground.
N89°48'41"W - 1305.04'

1/4 Corner:
Found and accepted 2.5". 1982 Duchesne County Surveyor Aluminum cap protruding 0.4' above ground, inline with East West running fence, North South running fence is 0.5' East of cap. As Reference Points to the Monument we set 2, 5/8" Rebar's with Blue Plastic Caps Stamped (LS 8704293) which bear N89°12'57"W 35.37' and S00°03'45"W 42.25' from the corner.

South 1/16 Corner:
Found and accepted Yellow Plastic
Cap (Stamped LS 148951) on 5/8"
rebar protruding 1.4' above ground.

Section Corner: S29|S28
Found and accepted 2.5", 2010 Duchesne County Surveyor Aluminum cap, flush with surface of road. As Reference Points to the Monument we set 2, 5/8" Rebar's with Blue Plastic Caps Stamped (LS 8704293) which bear N31°41'26"E 66.81' and S38°36'22"E 50.14' from the corner.

SURVEYOR'S NARRATIVE

DURING THE COURSE OF A SURVEY FOR ONE OF OUR CLIENTS. WE FELT IT NECESSARY TO PREPARE THIS PLAT.

DURING THE COURSE OF THIS SURVEY WE REFERRED TO THE FOLLOWING:

- GOVERNMENT LAND OFFICE SURVEYS.
- SURVEY #2518, FILED WITH THE SURVEYOR'S OFFICE OF DUCHESNE COUNTY, UTAH

BEARINGS ARE BASED UPON A LOCAL CARTESIAN GRID WHICH WAS CALIBRATED TO GEODETIC NORTH AT THE SOUTHEAST CORNER OF SECTION 36, T2S, R1W, U.S.M. AND HAS A PROJECT HEIGHT OF 5100 FEET.

BASIS OF BEARINGS FOR THIS SURVEY IS THE EAST LINE OF THE NORTHEAST QUARTER OF SECTION 30, T2S, R1W, U.S.B.&M. WHICH IS TAKEN FROM SAID LOCAL CARTESIAN GRID TO BEAR N00°01'51"W.

TRIMBLE GLOBAL POSITIONING SATELLITE EQUIPMENT WAS USED IN PERFORMANCE OF THIS SURVEY.

SURVEYOR'S CERTIFICATE

I BROCK J. SLAUGH, DO HEREBY CERTIFY THAT I AM A PROFESSIONAL LAND SURVEYOR AND THAT I HOLD CERTIFICATE #8704293 AS PRESCRIBED BY THE LAWS OF THE STATE OF UTAH. I FURTHER CERTIFY THAT THIS PLAT AND ITS COMPUTATIONS AND FIELD SURVEYS NECESSARY FOR THE DATA COMPILED HEREON WERE MADE BY ME OR UNDER MY DIRECT SUPERVISION AND THAT THE SAME ARE TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF.

BEST OF MY KNOWLEDGE AND BELIEF.
 No. 8704293
 05-08-2016
 BROKER
 SLAUGH
 [Signature]
 PROFESSIONAL LAND SURVEYOR
 LICENSE NO. 8704293
 STATE OF UTAH

SURVEYED BY: T.A.
DRAWN BY: M.W.W.
DATE: 12-5-15
SCALE: 1" = 400'
DATE REVISED:

TIMBERLINE
Engineering & Land Surveying
209 North 300 West • Vernal, Utah
(435) 789-1365

County Surveyor File # 3261

LEGEND

▲ = SECTION CORNER LOCATED

△ = SECTION CORNER LOCATED NOT MONUMENTED

NOTES:
UTILITIES, EASEMENTS, IMPROVEMENTS AND
ENCROACHMENTS NOT SHOWN ON THIS PLAT MAY EXIST.

S30 | S29

1/4 Corner:
Found and accepted 2.5", 1979 Aluminum cap protruding 1.3' above ground, surrounded by a mound of stones, 2.5' base, 0.8" high, inline with North running fence. Steel post 2' West of cap. As Reference Points to the Monument we set 2, 5/8" Rebar's with Blue Plastic Caps Stamped (LS 8704293) which bear N01°04'47" E 51.85' and N88°17'21" E 51.25' from the corner.

Sec. 30

Sec. 29

N00°01'51"W (Basis of Bearings) 2651.48'